

HIGHLANDS NEIGHBORHOOD RECONSTRUCTION PROJECT  
 LIGHTING SURVEY NO. 3  
 May 2, 2008

ADDRESS	Returned Survey	Rank Lighting Options				COMMENTS
		Most Desirable to Less Desirable				
		Option 1 \$1,100/REU	Option 2 #1,900/REU	Option 3 \$2,000/REU	Option 4 \$2,300/REU	
5313 Ayrshire	1		3	2	1	Option 1 is not acceptable, not enough lighting for safety.
5308 Ayrshire	1	3	2	1	4	
5300 Glenbrae Cir						
5225 Lochloy Dr	1	1	2	4	3	
5301 Glenbrae Cir	1					Reject all options. Please excavate and rewire for the 12 existing lights w/no immediate change in pole or fixture. The old wiring could be recycled rebate/credit back to the n'hood from the old copper.
5229 Lochloy Dr	1					Reject all options. None of these options are acceptable. Please listen to what professional experts are advising Bob Tengdin.
5209 Doncaster Way	1	4	3	2	1	Concern with paying for lighting which should be a basic service the City of Edina provides. Will we next be asked to pay for new stop signs?
5273 Lochloy Dr	1	1	4	4	4	
5305 Ayrshire	1	4	3	1	2	For just a bit more, we can have a good looking n'hood. The existing wooden poles are horrible looking!
5261 Lochloy Dr	1	4	4	3	1	Please consider installing lights that can use more energy-efficient methodology, such as LED. Please replace lights at the same time the wiring is done. Please get this whole project done before winter.
5241 Lochloy Dr	1	4	2	4	4	We request that you only repair/excavate/trench those lights that are not functioning properly and have not been fixed in recent years. The use of LED lighting should be closely studied. No new lights should be installed at this time.
5301 Ayrshire	1	3	2	1	4	
5248 Lochloy Dr	1	4	1	2	3	
5228 Duncraig	1					Reject all options. What has happened with LED lighting? Have the City Engineers heard what the climate control comm have been working on the LED. Seems that a huge rush by the City Engineer has not allowed that office to hear what others are working on in Edina.
5232 Duncraig	1					Reject all options. This survey appears to be from the City Engineers Dept. (specifically, Jack Sullivan). Where is the input from the n'hood lighting committee? It was my understanding that this was to be a cooperative effort. Also, I thought there was to be a feasibility study of LED lighting.
5268 Lochloy Dr	1					Reject all options. Letter attached.
5309 Ayrshire	1	4	2	1	3	
5213 Doncaster Way	1					Reject all options. Feel the city could excavate and rewire the 12 existing lights with no change to the pole or fixture. This would set things up for future change - possibly, LED lighting or a more energy efficient light. Thank you for hearing out input.
5240 Lochloy Dr	1					Reject all options. We/I agreed that you didn't work with the lighting committee. See attached May 3 letter recommendations from the committee.
5312 Ayrshire	1	1	2	3	4	
5321 Ayrshire	1	4	4	1	3	
5224 Lochloy Dr	1					Needs to be reviewed by the lighting committee before being sent out.
5245 Lochloy Dr	1					Reject all options. None of the above. Repair where necessary.
5281 Lochloy Dr	1					Reject all options. Only rewire 12 lights. Provide recycling rebate credit on all copper removed when rewiring. Consider LED lighting.
5201 Duncraig	1	4	3	2	1	
5215 Lochloy Dr	1	2	3	1	4	
5249 Lochloy Dr	1					Rejected as the committee recommends until amended and approved by n'hood.
5229 Duncraig	1	4	4	4	4	
5252 Lochloy Dr	1	3	2	1	4	
5205 Duncraig	1					LED Lights
5232 Lochloy Dr	1					Reject all options. The city should excavate existing wire and rewire for 12 of the existing lights. No immediate changes in poles or fixtures. A credit for all wire that is removed or existing lights for copper recycling credit. What is the possibility of LED lights being used in this project? shoebox lights are best option and least costly. Why are these not given as an option?
5272 Lochloy Dr	1					Reject all options. As suggested by a n'hood lighting committee: excavate and rewire; recycling rebate/credit; LED lighting; see survey for additional comments.
5236 Lochloy Dr	1					Reject all options; excavate and rewire; explore installing LED;
5325 Ayrshire	1	3	1	4	2	
5217 Lochloy Dr	1	3	2		1	
5221 Duncraig	1	2	1	3	4	n'bors. The road is one way and usual blocked for access. You could pull the light and save the expense. You might want to check this out.
5316 Ayrshire	1			1	2	
5244 Lochloy Dr	1	4	3	1	2	
5225 Duncraig	1	4	4	4	4	Please talk to our n'hood lighting committee re: the best option.
5217 Duncraig	1	1				
5209 Lochloy Dr	1	1				Option 1 using existing cobrahead lights.
5201 Lochloy Dr	1					Reject all options.
<b>Total Surveyed = 74</b>	<b>41</b>	<b>68</b>	<b>57</b>	<b>50</b>	<b>65</b>	
	74	55%				

\* Note: Lowest ranking score indicates the preferred option.